



---

## CASE HISTORY



**Project: Paper Mill Main Clarifier  
Joint and Crack Repair**

**Injection Duroseal Inject 2000  
System:**

**Area: 2,000 Linear Feet**

**Completed: August 1999**

In Eastern Maine, Paper mill officials noticed some effluent leaking from beneath the Mill's Main Clarifier. Jean's Waterproofing was contacted and along with mill engineers, decided that during the next scheduled shutdown the clarifier would be drained and washed. Then Jean's Waterproofing would inject every joint and random crack using Duroseal Inject 2000. The project was completed successfully and ahead of schedule.

There has been no known evidence of any further leakage from this structure.



---

**Corporate Office:**  
**Jean's Waterproofing, Inc.**  
**P.O. Box 1688 923 Minot Avenue**  
**Auburn, Maine 04211-1688**  
**(800) 458-2374**

**New York Division:**  
**Jean's Waterproofing, Inc.**  
**405 Tarrytown Road**  
**White Plains, NY 10607**  
**(914) 924-4530**

**Texas Division:**  
**Jean's Waterproofing, Inc.**  
**226 Trade Center Drive**  
**New Braunfels, TX 78130**  
**(830) 627-1769**